A8R-SL Packing List										
NO.	QTY	NAME	PICTURE	NO.	QTY	NAME	PICTURE			
1	1	Left Frame Module (Include Motherboard module and Left support plate)		21	2	350mm Rod				
2	1	Right Frame Module (Include power supply and Right Support Plate)		22	2	350mm Threaded Rod				
3	1	Front Plate (include Y belt bearing)	RAISCUBE	23	4	388mm Rod				
4	1	Frame CrossBeam	ENISCUBE T	24	2	420mm Threaded Rod				
5	1	Back Plate		25	2	Panel Cable	TO RECORD THE SERVE SERVE STREET ON ARM SEARCH			
6	1	Middle Bottom Plate (Include Z end- stop)		26	2	Belt				
7	2	Top Lock Plate (Left and right)		27	10	Zip Tie				
8	1 kit	Filament Rack		28	1	Hotbed	The state of the s			
9	1	Panel Control		29	1	"H" Module (Include H plate and 4 linear bearings)				
10	2	Z Axis Stepper	left right	30	1	SD Card Reader	S COSCI DAGWITH STATES AND STATES			

11	1	Y Axis Stepper (include Y End- Stop)		31	1	SD Card	Kingstort  SET S  SET S  SECOND PART  SET S  SET		
12	1	Extruder Module		32	1	PC Masking Sheet			
13	1	Left Link Block (Include Stepper, M6*45 Socket Screw)		33	1	0.25kg Filament			
14	1	Right Link Block (Include M8*15 Set Screw and Spacer		34	1	1.5m USB Cable	USB 2.0 CABLE  Wide William  White William  White William		
15	2	M3X12 (For Panel Control)		35	1	1.5m Power Line	90		
16	9	Tools	ATT TO						
17	30	M3X10	444 444 444 444 444 444 444 444 444 44	M3X10 Socket Cap Screws are widely used elsewhere.					
18	6 kits	P Clamp and Screw Set	666669	M4X6 Phillips Button Head Screw 12mm P Type Clamps					
19	12 kits	M8 Nut set	000000000000000000000000000000000000000	Nuts for 420mm Threaded Rods, each set includes M8 nut, washer and spacer.					
20	4 kits	Hotbed Fastener Set		Hotbed M3*25 Phillips scew, M3 nut, Spring and "M3 knurled cap nut"					